

# Oil Field Environmental Incident Summary

**Incident:** 20140906165037      **Date/Time of Notice:** 09/06/2014 16:50  
**Responsible Party:** OXY USA INC.  
**Well Operator:** OXY USA INC.  
**Well Name:** STATE FRANK BUTLER 1-29-32H-142-94  
**Field Name:** MURPHY CREEK      **Well File #:** 22881  
**Date Incident:** 9/6/2014      **Time Incident:** 12:10      **Facility ID Number:**  
**County:** DUNN      **Twp:** 142      **Rng:** 94      **Sec:** 29      **Qtr:**  
**Location Description:**

**Submitted By:** Robyn Espinoza      **Received By:**  
**Contact Person:** Robyn Espinoza  
5 GREENWAY PLAZA STE 110  
5 Greenway Plaza, Suite 110  
HOUSTON, TX 77046-0506

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile  
**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident** Treater Leak

**Release Contained in Dike** No      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	11	Barrels	10	Barrels	10	barrels
<b>Brine</b>						
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 9/29/2014      **Clean Up Concluded:** 9/23/2014

**Risk Evaluation:**

Contaminated surface material off location.

**Areal Extent:**

Inside the treater dike and a light mist offsite onto the adjacent land.

**Potential Environmental Impacts:**

Contaminated surface material off location.

**Action Taken or Planned:**

Rud Transportation was dispatched immediately to recover all standing liquids, the affected vegetation will be cut and bagged and all other contaminated material will be removed and disposed of.

**Wastes Disposal Location:** TBD

**Agencies Involved:**

**Updates**

---

**Date:** 9/8/2014

**Status:** Reviewed; Followup Required

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to treater leak, got off location. Followup is necessary.

---

**Date:** 9/9/2014

**Status:** Inspected; More Followup Required

**Author:** Cooper, Mike

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

The weather was 43 °F, cloudy, with wind from the northeast at 10 mph. The spray occurred on the east side of pad, on the vegetation at the edge of the pad and the fence line. Crop field does not appear to be impacted at this time. Vegetation has been mowed and bagged up. The bags are located on the north side of the pad near the entrance.

Followup is required in the future to check on the vegetative growth.

---

**Date:** 7/20/2015

**Status:** Post-inspection Update

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 15:14. The weather was sunny, 75°F, with the wind from the northwest 10-15 mph. The vegetation has come back in the area that was sprayed. The field next to the well pad is growing a crop. No further follow-up needed.